Kodak i2900 Series Scanners Software Release Notes

Version CD 3.01 Summary

Purpose of Release: This is a CMS release of drivers for the Kodak i2900 Series Scanners.

Note: When installing a Kodak i2900 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v1.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date: November 11th, 2015

 CD Version:
 3.01

 Twain:
 14.1

 Driver.dll:
 4.5

 Twaingui:
 6.8.2

 Hippo.dll:
 52.14

 Device.dll:
 5.2

 DeviceManager.dll:
 1.22

ISIS driver: 1.1.11508.6002

Legal Flatbed bundle: 3.3

Smart Touch App 1.8.37.181

New Driver Features:

- Added Orange as a default color dropout option
- Added Magnification Calibration for China Customers

Smart Touch Features/Fixes

None

Issues Fixed:

• Scanner can sometime freeze and stop scanning in the middle of a batch

Known Issues:

None

Version CD 3.0 Summary

Purpose of Release: This is a CMS release of drivers for the Kodak i2900 Series Scanners.

Note: When installing a Kodak i2900 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v1.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date: July, 27th, 2015

CD Version: 3.0
Twain: 14.1
Driver.dll: 4.3
Twaingui: 6.7
Hippo.dll: 52.13
Device.dll: 5.1
DeviceManager.dll: 1.19

ISIS driver: 1.1.11410.6002

Legal Flatbed bundle: 3.2

Smart Touch App 1.8.37.181

New Driver Features:

1. Addition of Arabic

Smart Touch Features

- 1. Addition of Arabic
- 2. Moved to version 1.8 (without Barcode)

Issues Fixed:

- 1. Customer's application hangs when canceling a scan
- 2. Color scanning will do auto rotation but B&W scanning will not auto rotate
- 3. When different rotation setting are applied in dual stream an error occurs.
- 4. Installation fails with Korean character "User Account" and/or "Computer Name"

Known Issues:

None

Version CD 2.0 Summary

Purpose of Release: This is a CMS release of drivers for the Kodak i2900 Series Scanners. Note: When installing a Kodak i2900 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware v1.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date: November 7th, 2014

CD Version: 2.0 Twain: 13.0 Driver.dll: 3.0 5.36 Twaingui: Hippo.dll: 52.12 Device.dll: 4.0 1.13 DeviceManager.dll:

ISIS driver: 1.1.11405.29001

Legal Flatbed bundle: 2.0 **Smart Touch App** 1.7.114

New Driver Features:

2. None

Smart Touch Features

3. Updated the OCR engine

Issues Fixed:

5 None

Known Issues:

None

Version CD 1.05 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2900 Series Scanners. Note: When installing a Kodak i2900 scanner on a host PC for the first time the Full

Install CD (shipped with the scanner) must be used. If the InstallSoftware v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware v1.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

December 20th, 2013 Date:

CD Version: 1.09 Twain: 12.15 Driver.dll: 12.16 Twaingui: 5.25 Hippo.dll: 52.9 Device.dll: 3.12

DeviceManager.dll: 1.11

ISIS driver: 1.1.11311.6001

Bundled A4 Flatbed 1.12

New Driver Features:

3. None

Smart Touch Features

4. None

Issues Fixed:

1. Fixed multi-feed leave paper in path handling

Known Issues:

None

Version CD 1.05 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2900 Series Scanners.

Note: When installing a Kodak i2900 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v1.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date: July 15th, 2013

CD Version: 1.05
Twain: 12.11
Driver.dll: 12.12
Twaingui: 5.18
Hippo.dll: 52.6
Device.dll: 3.11
DeviceManager.dll: 1.4

ISIS driver: 1.1.11303.12001

Bundled A4 Flatbed 1.10

New Driver Features:

4. None

Smart Touch Features

5. None

Issues Fixed:

- 2. Receiving TWRC Error. Scanner also displays a 2-3 second delay between scans (memory issue resolutions over 300dpi should only use 1 image buffer)
- 3. Scanner always scans in page on demand mode after Scan One Page
- 4. Scan application crashes when twain is opened/closed/opened within the same process

Known Issues:

None

Version CD 1.04 Summary

Purpose of Release: This is a CSM release of drivers for the Kodak i3000 Series Scanners.

Note: When installing a Kodak i3000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v1.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date: May 14th, 2013

CD Version: 1.04
Twain: 12.11
Driver.dll: 12.12
Twaingui: 5.18
Hippo.dll: 52.6
Device.dll: 3.11
DeviceManager.dll: 1.4

ISIS driver: 1.1.11303.12001

Bundled A4 Flatbed 1.9

New Driver Features:

- 5. Support for Windows Server 2012
- 6. Support for Ubuntu 12.04 LTS
- 7. Improved Document Protection Algorithm

Smart Touch Features

6. None

Issues Fixed:

- 1. No error was displayed on the OCP or the Operator Log when the Pod interlock is open at power up or at the start of a scan
- 2. The ISIS Image #2 was not using the correct Perfect Page profile settings in Windows 8
- 3. Updated the User's Guide
- 4. ISIS help files were updated

Known Issues:

None