Kodak alaris

Kodak i1100 Series Scanners Windows Drivers Release Notes

Version CD 2.26 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i1150 Scanner.
Note: When installing a Kodak i1150 Scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Instructions for installing drivers using the ISO file:
For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount) For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

Date:	**September 11, 2017**
CD Version:	**2.26**
Firmware	**1.35 (separate file, not part of CD) for i1150/i1190**
Firmware	**1.32 (separate file, not part of CD) for i1180/i1190E**
Twain:	**14.6**
Driver.dll:	**4.9**
Twaingui:	**8.1**
Hippo.dll:	**52.35**
Device.dll:	**4.6**
DeviceManager.dll:	**1.20**
ISIS driver:	**1.1.11609.30001**
Smart Touch App	**No Longer on CD**

Change Requests Implemented:
1. DIAS-1136 – Many changes to Automatic Rotation to support credit card scanning which are dark and have limited text printed on them.
2. DIAS-1225 –Remove SmartTouch from installation media
3. DIAS-1226 – Remove Capture Pro LE from installation media
4. DIAS-1284 – Update Installer with link to Smart Touch and Capture Pro LE internet downloadable files.

Driver Issues Fixed:
1. DIAS-1198 Address a Citrix connectivity issue
2. DIAS-1126-Address issue with Windows VM using USB Redirection

Firmware Issues Fixed:
1. None

Kodak i1100 Series Scanners Windows Drivers Release Notes

Known Issues:
1. PR 25176: CD 2.04 and higher will not install on "Server 2008-R2" and "Server 2012-R2"
   a. Workaround
      i. .NET Framework 3.5 or higher must be installed
      ii. Desktop Experience must be installed
      iii. Must be logged in as administrator
      iv. Must right click on set_up.exe and use can install via Run as administrator

Kodak alaris

Kodak i1100 Series Scanners Windows Drivers Release Notes

Version CD 2.16 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i1150 Scanner.

> Note: When installing a Kodak i1150 Scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	**January 9, 2017**
CD Version:	**2.16**
Firmware	**1.35 (separate file, not part of CD) for i1150/i1190**
Firmware	**1.32 (separate file, not part of CD) for i1180/i1190E**
Twain:	**14.5**
Driver.dll:	**4.8**
Twaingui:	**8.1**
Hippo.dll:	**52.30**
Device.dll:	**4.4**
DeviceManager.dll:	**1.17**
ISIS driver:	**1.1.11609.30001**
Smart Touch App	**1.8.68.475**

New Driver Features:

5. CR 5370 - Add QR Barcode reading
6. CR 5276 - Add 64-bit TWAIN driver
7. CR 5119 - Do not Install ISIS on Windows XP Operating System computers

Smart Touch Features/Fixes:

1. PR 26539 - When scanner wakes from sleep mode, it no longer connects
2. CPSOLSTS-101/202 - Smart Touch not sending paper source information
3. PR 26223 - When you set the searchable PDF of the i1190 SmartTouch it shows Arabic as an option
4. CPSOLSTS-163 - Folder permissions are being changed when users are scanning
5. CPSOLSTS-164 – SmartTouch won't install when a folder redirection of the users' home directories to a server has been moved
6. CPSOLSTS-166 - The date is being repeated in the filename string
7. CPSOLSTS-186 - SmartTouch upgrade does not always happen correctly when running silently

Driver Issues Fixed:

1. PR 26946 - i1150 when scanning 2D barcode with TWAIN or ISIS Driver

2. PR 26840 - problem when scanning dark hard cards (credit cards)
3. PR 25842 - Unable to communicate with scanner after PC comes out of Sleep Mode
4. PR 25701 - When using Blank page removal, an image that is not blank is being deleted
5. DIAS-507- WIA version not updating with i11xx CD v2.14 upgrade [Smart Touch scanner buttons don't work, but Smart Touch in system tray works]
6. DIAS-889 - Smart Touch Buttons on OCP not functioning in Windows XP

Firmware Issues Fixed:
2. DIAS-478: Scanner errors on OCP can be over written on startup
3. CD 5390 - Increase the feeder clutch on time from 10mm to 20mm - also in FW 1.32

Known Issues:
2. PR 25176: CD 2.04 and higher will not install on "Server 2008-R2" and "Server 2012-R2"
   a. Workaround
      i. .NET Framework 3.5 or higher must be installed
      ii. Desktop Experience must be installed
      iii. Must be logged in as administrator
      iv. Must right click on set_up.exe and use can install via Run as administrator

Kodak i1100 Series Scanners Windows Drivers Release Notes

Kodak i11xx Series Scanners Software Release Notes
Version CD 2.07.01 Summary

Purpose of Release: This is a LPO release to the drivers for the Kodak i3000 scanners which allows the locking of a specific customer application to occur such that the TWAIN driver will only work with this one specific application.

Date:	**November 9, 2016**
CD Version:	**2.07.01**

Kodak i1150 Scanner Software Release Notes

Version CD 2.07 Summary

Purpose of Release: This is a CSM release of drivers for the Kodak i1150 Scanner.

> Note: When installing a Kodak i1150 Scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	**January 30th, 2016**
CD Version:	**2.07**
Firmware	**1.21**
Twain:	**14.2**
Driver.dll:	**4.3**
Twaingui:	**6.7**
Hippo.dll:	**52.26**
Device.dll:	**4.1**
DeviceManager.dll:	**1.14**
ISIS driver:	**1.1.11512.4001**
Smart Touch App	**1.8.43.247**

New Driver Features:
8. Increase to 30ppm from 25ppm
9. Change to default profile: Turned off Hole fill and Streak Removal

Smart Touch Features
1. None

Issues Fixed:

7. None

Known Issues:

None

Version CD 2.01 Summary

Purpose of Release: This is a CSM release of drivers for the Kodak i1150 Scanner.

Note: When installing a Kodak i1150 Scanners on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	**November 18, 2014**
CD Version:	**2.01**
Firmware	**1.04.02**
Twain:	**13.1**
Driver.dll:	**13.6**
Twaingui:	**5.36**
Hippo.dll:	**52.24**
Device.dll:	**4.2**
DeviceManager.dll:	**1.9**
ISIS driver:	**1.1.11404.29001**
Smart Touch App	**1.8.18.104**

New Driver Features:
10. Add error message for no image data
11. Mac Drivers Available
12. Mac - PageManager - Scan Button was launched and added to the system tray
13. Add JPEG and G4 Compressions to PageManager
14. Expand Linux support to 64-bit for Ubuntu 14.04 (LTS)
15. Develop Mag Adjustment Tool Mag for China Bank customers

Smart Touch Features
1. Have a silent installer option for Smart Touch patch (web) installer
2. Ability to not create a copy of the file on the PC when emailing a document
3. Add the name WebDAV to Custom Cloud
4. Add 'create folder' icon to configure cloud storage screen
5. Support Scan to Google Drive (CloudStorage)
6. Hide 'delete file after sending' option when change to non-mail destination

Issues Fixed:
8. None

Known Issues:
None