

# Kodak i2000 Series Scanners Software Release Notes

## Version CD 4.14 Summary

**Purpose of Release:** This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

<b>Date:</b>	<b>December 14, 2016</b>
<b>CD Version:</b>	<b>4.14</b>
<b>Smart Touch</b>	<b>1.8.67.448</b>
<b>Twain:</b>	<b>14.7</b>
<b>Driver.dll:</b>	<b>4.11</b>
<b>Twaingui:</b>	<b>8.1</b>
<b>Hippo.dll:</b>	<b>52.39</b>
<b>Device.dll:</b>	<b>5.5</b>
<b>DeviceManager.dll:</b>	<b>1.80</b>
<b>ISIS driver:</b>	<b>2.0.11508.25002</b>
<b>Flatbed4/bundle:</b>	<b>No longer bundled</b>
<b>Flatbed3/bundle</b>	<b>No longer bundled</b>

### **New Driver Features:**

1. 64 Bit TWAIN Driver is available

### **Smart Touch Features Fixed**

1. Smart Touch Configure Screen Strings missing intermittently
2. Folder permissions being changed when users are scanning
3. ST won't install when a folder redirection of the users' home directories on a server has been moved.
4. the date is being repeated in the filename string.

### **Driver Issues Fixed:**

1. LCD Contrast Setting for i2x20 scanners is adjustable for FE Key
2. Linux Driver will run on computer with more than 19 cores
3. Unable to communicate with scanner after PC comes out of Sleep Mode
4. Various Manufacturing End of Line Process Issues

### **Known Issues:**

None

# **Kodak i2000 Series Scanners Software Release Notes**

## **Version CD 4.06.1 Summary**

**Purpose of Release:** This is a general release to the drivers for the Kodak i2x20 scanners which allows the service diagnostics keys for Scan Validation Tool to continue to function after October 12, 2016. No other changes from DVD 4.06 are included

**Date:** October 12, 2016

**CD Version:** 4.06.01

# Kodak i2000 Series Scanners Software Release Notes

## Version CD 4.06 Summary

**Purpose of Release:** This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

<b>Date:</b>	<b>March 1<sup>st</sup>, 2016</b>
<b>CD Version:</b>	<b>4.06</b>
<b>Smart Touch</b>	<b>1.8.37.177</b>
<b>Twain:</b>	<b>14.4</b>
<b>Driver.dll:</b>	<b>4.7</b>
<b>Twaingui:</b>	<b>6.7</b>
<b>Hippo.dll:</b>	<b>52.35</b>
<b>Device.dll:</b>	<b>5.4</b>
<b>DeviceManager.dll:</b>	<b>1.74</b>
<b>ISIS driver:</b>	<b>2.0.11508.25002</b>
<b>Flatbed4/bundle:</b>	<b>No longer bundled</b>
<b>Flatbed3/bundle</b>	<b>No longer bundled</b>

### **New Driver Features:**

5. Add-support for "Orange and Red" color-dropout as a default option
6. Support Windows XP through 2016 (TWAIN only)
7. Remove ISIS XP support

### **Smart Touch Features Fixed**

5. Scan to Word and Excel
6. Barcode
7. Scan to the cloud

### **Driver Issues Fixed:**

1. ISIS ONLY: Receive "Unknown error. (-4523)" error message for White and Black fill color settings for Image Edge Fill with Color Photograph profile.

### **Known Issues:**

None

# **Kodak i2000 Series Scanners Software Release Notes**

## **Version CD 2.21 Summary**

**Purpose of Release:** This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

<b>Date:</b>	<b>June 27<sup>th</sup> , 2014</b>
<b>CD Version:</b>	<b>2.21</b>
<b>Smart Touch</b>	<b>1.7.116</b>
<b>Twain:</b>	<b>12.12</b>
<b>Driver.dll:</b>	<b>2.15</b>
<b>Twaingui:</b>	<b>5.34</b>
<b>Hippo.dll:</b>	<b>52.17</b>
<b>Device.dll:</b>	<b>3.11</b>
<b>DeviceManager.dll:</b>	<b>1.66</b>
<b>ISIS driver:</b>	<b>2.0.11211.6001</b>
<b>Flatbed4/bundle:</b>	<b>2.17</b>
<b>Flatbed3/bundle</b>	<b>2.17</b>

### **New Driver Features:**

8. Fine tuned the algorithm used for content based blank page deletion
9. Reduced the size of the hole that hole fill uses
10. Changed the name of Blank Image Detection to Blank Image Deletion
11. Using the new Graphical Icons

### **Smart Touch Features Fixed**

1. Replaced the OCR engine
2. Changed the URL used for BOX

### **Driver Issues Fixed:**

1. Fixed the issue when changing the Max length of a document, it did not "stick"

### **Known Issues:**

None

# Kodak i2000 Series Scanners Software Release Notes

## Version CD 2.15 Summary

**Purpose of Release:** This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

<b>Date:</b>	<b>October 11<sup>th</sup>, 2013</b>
<b>CD Version:</b>	<b>2.15</b>
<b>Smart Touch</b>	<b>1.7.85</b>
<b>Twain:</b>	<b>12.9</b>
<b>Driver.dll:</b>	<b>2.10</b>
<b>Twaingui:</b>	<b>5.19</b>
<b>Hippo.dll:</b>	<b>52.14</b>
<b>Device.dll:</b>	<b>3.8</b>
<b>DeviceManager.dll:</b>	<b>1.64</b>
<b>ISIS driver:</b>	<b>2.0.11211.6001</b>
<b>Flatbed4/bundle:</b>	<b>2.16</b>
<b>Flatbed3/bundle</b>	<b>2.16</b>

### **New Driver Features:**

None

### **Smart Touch Features Fixed**

3. Corrected the issue when reviewing documents in the viewer, the scaling randomly changes
4. Updated the Attribution which was missing information on Win 7 64 bit OS

### **Driver Issues Fixed:**

1. Fixed page-on-demand duplex scanning issue

### **Known Issues:**

None

# Kodak i2000 Series Scanners Software Release Notes

## Version CD 2.11 Summary

**Purpose of Release:** This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

<b>Date:</b>	<b>June 26<sup>th</sup>, 2013</b>
<b>CD Version:</b>	<b>2.11</b>
<b>Twain:</b>	<b>12.8</b>
<b>Driver.dll:</b>	<b>2.8</b>
<b>Twaingui:</b>	<b>5.19</b>
<b>Hippo.dll:</b>	<b>52.14</b>
<b>Device.dll:</b>	<b>3.7</b>
<b>DeviceManager.dll:</b>	<b>1.56</b>
<b>ISIS driver:</b>	<b>2.0.11211.6001</b>
<b>Flatbed4/bundle:</b>	<b>2.11</b>
<b>Flatbed3/bundle:</b>	<b>2.11</b>

### New Driver Features:

1. Added Arabic User's Guide to master CD
2. Attribution update for current dating

### Smart Touch Features

None

### Issues Fixed:

None

### Known Issues:

None

# Kodak i2000 Series Scanners Software Release Notes

## Version CD 2.09 Summary

**Purpose of Release:** This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full

Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

**Date:** April 15<sup>th</sup>, 2013  
**CD Version:** 2.09  
**Twain:** 12.5  
**Driver.dll:** 2.6  
**Twaingui:** 5.6  
**Hippo.dll:** 52.3  
**Device.dll:** 3.5  
**DeviceManager.dll:** 1.5  
**ISIS driver:** 2.0.11211.6001  
**Flatbed4/bundle:** 2.6  
**Flatbed3/bundle:** 2.6

#### **New Driver Features:**

3. New ISIS driver
4. Supports Ubuntu 12.04 LTS

#### **Smart Touch Features**

None

#### **Issues Fixed:**

1. New translated publications added to the CD

#### **Known Issues:**

None

### **Version CD 2.06 Summary**

**Purpose of Release:** This is a CSM release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

**Date:** November 30<sup>th</sup>, 2012  
**CD Version:** 2.06  
**Twain:** 12.5  
**Driver.dll:** 2.6  
**Twaingui:** 5.6  
**Hippo.dll:** 52.3  
**Device.dll:** 3.5  
**DeviceManager.dll:** 1.5

**ISIS driver: 2.0.11204.11001**

**Flatbed4/bundle: 2.6**

**Flatbed3/bundle 2.6**

**New Driver Features:**

1. Support for Windows 8 (32-bit and 64-bit)
2. Auto shutoff feature to meet EuP requirements

**Smart Touch Features**

1. Scan to the “Cloud” (Box.net, Evernote and other cloud apps using Webdev)
2. Silent installer option

**Issues Fixed:**

2. ECDO color names were not translated in Japanese
3. JPEG superior Quality level was 90, it is now 100
4. Smart Touch now launches Outlook 64-bit
5. Smart Touch – Files were named incorrectly when using dual stream output

**Known Issues:**

None

**Version CD 1.17 Summary**

**Purpose of Release:** This is a CSM release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware\_v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v1.xx.exe may be used to update a host PC that used an Install CD Version 1.03 for its first install.

**Date: November 30th, 2011**

**CD Version: 1.17**

**Twain: 11.23**

**Driver.dll: 1.24**

**Twaingui: 4.42**

**Hippo.dll: 50.17.6.14**

**Device.dll: 1.21**

**DeviceManager.dll: 1.33**



**Flatbed4/bundle: 1.24**

**Flatbed3/bundle 1.16**

**New Driver Features:**

3. Support for Kodak A3 Flatbed Scanners
4. Support for “hot pluggable” Flatbed Scanners
5. Support for 500 dpi scanning
6. The Const.ini file is back for language support
7. Greek, Polish and Romanian User’s Guides have been added
8. Improved the throughput when scanning short documents (i.e checks)

**Smart Touch Features**

3. Ability to enter a carriage return into the Smart Touch shortcut name
4. Improve the speed of the OCR output
5. Provide additional options for file name formats

**Issues Fixed:**

6. When using Capture Desktop and using another language other than English, the scanner can’t be found
7. Lexicon Executor crashing error
8. CAP\_AUTOSCAN handling error
9. ISIS: Sheet Counter is not incrementing

**Known Issues:**

None

**Version CD 1.5.3 Summary**

**Purpose of Release:** Units are being built with either a Sony or Toshiba Camera. This version provides support for either camera.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner or downloaded from the Kodak Support Web site) must be used. If the InstallSoftware\_v1.53.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware\_v1.5.3.exe may be used to update a host PC that used an Install CD Version 1.03 for its first install.

**Date:** October 12<sup>th</sup>, 2011

**New Features:**

Support for Sony cameras

**Issues Fixed:**

None

**Known Issues:**