

Kodak i5000V Series Scanners Software Release Notes

DVD Version 2.2 Summary

Purpose of Release: This is a general release to the drivers for the Kodak i5250V, i5650V scanners which allows the service diagnostic keys for Scan Validation Tool to continue to function after October 12, 2016.

No other changes from DVD 2.2 are included.

Date: October 12, 2016

Versions (changed from last release):

Scan Validation Tool: 12.3.1

Kodak i5000V Series Scanners Software Release Notes

Version CD 2.1 Summary

Purpose of Release: This is the first release of drivers for the Kodak i5x50v Scanners. The main intent of this release is to support the new features and functions for the i5250V and i5650V Scanners with VRS Elite version 5.1

Date: June 6, 2016

Versions:

VRS (Kodak OEM)	5.1.0.0.1206 Professional
TWAIN driver:	14.6
ISIS driver:	(Not included)
Scan Validation Tool:	12.2
WIA:	6.6
Firmware:	(Not Included) use with 05.11.5

Supported Models:

Kodak i5250V
Kodak i5650V
Kodak i5200V (not QA Tested, new features not supported)
Kodak i5600V (not QA Tested, new features not supported)
Kodak i9000 (Ngenuity) (not QA Tested, new features not supported)

New Features from CD 1.4: (i5x50V only.)

1. Intelligent Printing – Patch Counting
2. Intelligent Document Protection
3. Patch Configurator
4. Hold Multifeeds at Exit Nip
5. Variable Print Size
6. Additional Date Time print options
7. Support Orange and Orange/Red ECDO Colors
8. Support 500 DPI image resolution

Improvements from CD 1.4:

1. See new Features

Notes:

- The testing for this release was done with scanner Firmware 05.11.05.
- The i5x50V scanner was designed specifically to support Kofax VRS. There is no ISIS “direct” ISIS driver installed. The Kodak direct TWAIN driver and SVT are included only for diagnostic support. The Kodak i5x50V scanners performance is severely limited when using the direct TWAIN driver.
- The i5x50V scanner should only be used with applications that support Kofax VRS.

Known Issues:

(none)

Kodak i5000V Series Scanners Software Release Notes

Version CD 1.4 Summary

Purpose of Release: This is the second release of drivers for the Kodak i5000v Scanners. The main intent of this release is to support Windows 8 which required VRS Elite version 5.1.0.

Date: May 29st, 2014

Versions:

VRS (Kodak OEM)	5.1.0474 Professional
TWAIN driver:	12.1
ISIS driver:	(Not included)
Scan Validation Tool:	9.25
WIA:	3.8
Firmware:	3.14.5

Supported Models:

Kodak i5200V
Kodak i5600V

New Features from CD 1.0: (See updated User Documentation for more details.)

9. Support for Windows 8
10. Update to VRS 5.1

Improvements from CD 1.0:

2. The Kodak OEM VRS 5.1.0 Professional version provided in this release includes all of the updates to Kofax VRS Elite 5.1.0 R2 (5.1.0078) and more. Please refer to the Kofax VRS 5.1.0 Release Notes on the Kofax web site for more information.
3. Updated User Documentation

Notes:

- The testing for this release was done with scanner Firmware 3.14.5. Kodak i5000V scanners with older versions of firmware should be updated to this version when installing this release.
- The i5000V scanner was designed specifically to support Kofax VRS. There is no ISIS "direct" ISIS driver installed. The Kodak direct TWAIN driver and SVT are included only for diagnostic support. The Kodak i5000V scanners performance is severely limited when using the direct TWAIN driver.
- The i5000V scanner should only be used with applications that support Kofax VRS.

Known Issues:

(none)

Kodak i5000V Series Scanners Software Release Notes

Version CD 1.0 Summary

Purpose of Release: This is the initial release of drivers for the Kodak i5000v Scanners.

Date: March 1st, 2012

Versions:

VRS (Kodak OEM)	5.0.953 Professional
TWAIN driver:	11.9
ISIS driver:	(Not included)
Scan Validation Tool:	8.9
WIA:	1.17

Supported Models:

Kodak i5200V
Kodak i5600V

Notes:

(none)